

2007 ASTONDOA 59 GLX – M/Y CRINGA III



MAIN YACHT CHARACTERISTICS:

Boat Name:	CRINGA III	Year:	2007
Builder/Make:	Astondoa	Model:	59 GLX
Hull Number:	07	Type:	Motor Yacht
Length Overall:	59ft 7in 18.20m	Beam:	17ft 2in 5.24m
		Draft:	3ft 9in 1.20m
Engine Make/Model:	2x MAN D2848LE 423 V8	Engine horsepower:	2x 900hp
Propulsion Type:	Shaft Drive	Fuel Type:	Diesel
Cruising Speed:	22 knots	Max Speed:	30 knots
Engine Hours:	2595	Range:	250 nautical miles
Guest Cabins:	3	Crew Cabins:	1
Total Guests:	6	Total Crew:	2
Total Guest Toilets:	3	Crew Toilets:	1
On Display:	Girona	Country:	Spain
Flag:	Spanish	Private/Commercial:	Private
Asking Price:	€ 595,000	Tax Status:	VAT Paid (12% Spanish matriculation paid)

Disclaimer:

Brokers present the particulars of this Vessel in good faith; however, they cannot guarantee or warrant the accuracy of this information, nor do they provide any assurances regarding the Vessel's condition. Images of the Vessel may be sourced from a catalogue. This document shall not, under any circumstances, be deemed a contractual term.

2007 ASTONDOA 59 GLX – M/Y CRINGA III

TECHNICAL CHARACTERISTICS:

RCD / CE Category:	A - Ocean	Classifying Body:	RINA
Main Generator:	Cummins ONAN 19 kW	2nd Generator:	/
Hours:	N/A	Hours:	/
Fuel Tank:	2700 lt 713 gal	Water Tank:	900 lt 237 gal
Black Tank:	250 lt 66 gal	Grey Tank:	250 lt 66 gal
Stabiliser(s):	900 mm Humphree stabiliser interceptors	Bow Thruster:	Yes
Stern Thruster:	Yes	Air Conditioning:	Yes

YACHT DESCRIPTION:

Architect:	Astondoa Engineering Team	Material:	GRP
Internal Furniture:	Satin Light Oak	External Hull Colour:	White and Blue

M/Y CRINGA III is a beautifully maintained 2007 Astondoa 59 GLX that combines timeless Spanish design with extensive modern upgrades. Under her current ownership, she has benefited from an exceptional €880,000 investment between 2021 and 2026, transforming her into one of the finest examples of the model available today. Powered by twin 900 hp MAN engines, she delivers confident cruising with reliable performance, while her spacious flybridge, generous cockpit and elegant interiors make her equally suited to family cruising and entertaining. Professionally maintained throughout, CRINGA III presents a rare turnkey opportunity, ready to be enjoyed immediately without compromise.

LAYOUT:

CRINGA III accommodates up to six guests in a practical three-cabin layout, comprising a full-beam owner's suite aft, a forward VIP cabin and a port-side guest cabin, each benefiting from its own en-suite bathroom. The main saloon provides a bright and welcoming lounge with adjacent dining area, while the separate galley supports comfortable extended stays on board. Outside, the aft cockpit connects seamlessly with the saloon, creating an inviting entertaining space, while the flybridge offers generous seating, sunbathing areas and a second helm station. Separate crew accommodation with private bathroom ensures discreet service and additional flexibility.

BROKER COMMENTS:

CRINGA III is one of those yachts that simply stands out. More than €880,000 has been invested in her over the past five years and it shows in every detail. Meticulously maintained, technically up to date and presented in outstanding condition, she is ready to be enjoyed from day one. Opportunities to find a yacht of this calibre, maintained to such a high standard, are increasingly rare.

Disclaimer:

Brokers present the particulars of this Vessel in good faith; however, they cannot guarantee or warrant the accuracy of this information, nor do they provide any assurances regarding the Vessel's condition. Images of the Vessel may be sourced from a catalogue. This document shall not, under any circumstances, be deemed a contractual term.

2007 ASTONDOA 59 GLX – M/Y CRINGA III

SPECIFICATION:

EQUIPMENT:

General:

Extensive refit programme (2021–2026)
Approx. €880,000 invested

External:

Hydraulic bathing platform (1.20 m)
Burmese teak decking
New solid teak to side decks, foredeck and bathing platform
Hydraulic OPACMARE 4334/42 gangway
Flybridge bimini
Bow bimini
Carbon-fibre supported cockpit awning
Full exterior upholstery covers
Hydraulic swim ladder (Swissway)
Retractable stern shower
Flybridge galley
Flybridge refrigerator & freezer
Flybridge induction hob
Industrial ice maker
LED exterior lighting
Dimmable exterior lighting (DALI)
Warm illuminated Astondoa logos
Flybridge table lighting
Flybridge courtesy lighting
Port side access door
Stainless steel stern access door
Stainless steel cleat guards
Side rail openings
Protective covers throughout
Hydraulic platform servicing
Solar control window film

Internal:

Three en-suite guest cabins
Full-beam owner's suite
Separate crew cabin
Crew bathroom
Air conditioning
Smart TV in saloon
TVs in all cabins
Home automation lighting
Dimmable LED lighting
Satin light oak galley slats
Bespoke interior upholstery
Leather-upholstered master bed
New master headboards
Four new master mirrors
Guest cabin mirrors replaced
Interior restoration and detailing
White lacquer TV cabinet
Interior leather detailing
New curtains
Synthetic galley carpet
Additional cabin sockets

Disclaimer:

Brokers present the particulars of this Vessel in good faith; however, they cannot guarantee or warrant the accuracy of this information, nor do they provide any assurances regarding the Vessel's condition. Images of the Vessel may be sourced from a catalogue. This document shall not, under any circumstances, be deemed a contractual term.

2007 ASTONDOA 59 GLX – M/Y CRINGA III

SPECIFICATION (continued):

Interior LED lighting upgrade

Technical:

CUMMINS ONAN 19 kW generator (new 2024 and serviced annually)

Yacht Controller remote control

Bow thruster

Stern thruster

VETUS encapsulated stern thruster

HUMPHREE interceptor system

Third control station aft

HIGH PRESSURE SCA 260-2 watermaker (260 L/h)

Lithium battery bank

2500W pure sine wave inverter

Battery monitoring system

Electrical system completely reorganised

Relocated battery room

NMEA tank displays

Water level monitoring

New air-conditioning pump

Engine room LED lighting

New engine room ventilation

New freshwater pressure pumps

New hot water heater

Annual MAN engine servicing

Engine oil coolers replaced

High-pressure fuel pumps replaced

Injectors replaced

Cylinder heads replaced

TIDES shaft seals

Strut bearings

New stern propeller

Exhaust overhaul

Hydraulic steering overhaul

Steering piston overhaul

Power steering refurbishment

Engine batteries replaced

Bilge pumps upgraded

Water tanks serviced

Black water system serviced

Fuel tank ventilation filters

Anchor windlass serviced

New anchor chain (100 m)

New navigation lights

New mooring lights

Underwater anodes replaced

Dry docking

Antifouling

PropSpeed treatment

NAVIGATION:

2 × Raymarine GPS chartplotters

Raymarine radar

Raymarine autopilot

Raymarine Tridata

Raymarine rudder indicator

2 × DSC VHF radios

Remote-controlled LED searchlight

Disclaimer:

Brokers present the particulars of this Vessel in good faith; however, they cannot guarantee or warrant the accuracy of this information, nor do they provide any assurances regarding the Vessel's condition. Images of the Vessel may be sourced from a catalogue. This document shall not, under any circumstances, be deemed a contractual term.

2007 ASTONDOA 59 GLX – M/Y CRINGA III

SPECIFICATION (continued):

Long-range beacon
Starlink internet (mobile antenna installed 2025)

AUDIO VISUAL:

Interior & exterior sound system
Smart TV saloon
TVs in all cabins
Starlink internet

DOMESTIC:

Air conditioning
Dishwasher
Washing machine
Tumble dryer
Ceramic hob
Oven
Microwave
Refrigerator
Freezer
Flybridge refrigerator
Flybridge freezer
Flybridge induction hob
Industrial ice maker
Water heater
Watermaker
Outdoor power sockets

Disclaimer:

Brokers present the particulars of this Vessel in good faith; however, they cannot guarantee or warrant the accuracy of this information, nor do they provide any assurances regarding the Vessel's condition. Images of the Vessel may be sourced from a catalogue. This document shall not, under any circumstances, be deemed a contractual term.

2007 ASTONDOA 59 GLX – M/Y CRINGA III

LAYOUT:



Disclaimer:

Brokers present the particulars of this Vessel in good faith; however, they cannot guarantee or warrant the accuracy of this information, nor do they provide any assurances regarding the Vessel's condition. Images of the Vessel may be sourced from a catalogue. This document shall not, under any circumstances, be deemed a contractual term.